



NOTES:

1. REMOVE EXISTING PAVEMENT AND PAVEMENT SUBBASE UNDER ITEM 203.02

TYPICAL TRENCH IN PAVED AREA

NOT TO SCALE